# Oil Field Environmental Incident Summary

**Responsible Party:** EOG RESOURCES, INC. **Well Operator:** EOG RESOURCES, INC.

Well Name: PARSHALL 17 NWNW CENTRAL TANK BATTERY

Field Name: PARSHALL Well File #:

Date Incident:10/8/2016Time Incident:10:00Facility ID Number:228602-01County:MOUNTRAILTwp:152Rng:90Sec:17Qtr:NW NW

Location Description: onsite area around flare and offsite 100'x40' area mist

Submitted By: Danielle Dupay Received By:

Contact Person: Danielle Dupay

600 17TH ST STE 1000N DENVER, CO 80202

General Land Use: Pasture Affected Medium: Topsoil

**Distance Nearest Occupied Building:** 

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

**Brine** 

Other 5 Gallons 5 Gallons 5 gallons

**Description of Other Released Contaminant:** 

Exempt waste H2S scavenger

Inspected: Written Report Received: 1/3/2017 Clean Up Concluded: 10/5/2016

Risk Evaluation:

N/A

Areal Extent:

Misted pasture grasses 100'x40' area and 5 gallons onsite

# Potential Environmental Impacts:

N/A

# Action Taken or Planned:

The offsite misted grasses and soils were removed and will be disposed of. The liquids onsite were removed with vac truck along with some storm water. The offsite area will be re-seeded.

Wastes Disposal Location: Secure Disposal - Stanley ND

Agencies Involved: TAT and MHA

#### **Updates**

Date: 10/10/2016 Status: Reviewed - Assigned to Other Agency Author: O'Gorman, Brian

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

# Notes:

According to the report, 5 gallons of H2S scavenger were released and not contained. Incident is within MHA Nation. Report forwarded to MHA, BIA and EPA.